



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program August 23, 2012

Reviewed: PPAS

Mine Name: Dugway Pass	Permit Number: S/023/0091
Operator Name: Davies, Wingle & Davies, Inc	Inspection Date: August 23, 2012
Inspector(s): Wayne Western	Time: 11:00 – 11:30 am
Other Participants: none	Mine Status: ACT
Weather Condition: 77 degrees partly cloudy	Last Inspection: October 26, 2011
Bond Renewal Date: May 5, 2014	Bond Amount: \$25,200.00
Surface Ownership: SITLA	Mineral Ownership: SITLA
Last Year of Production: 2008	Acreage: 5 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This is a routine inspection.

Inspection Summary:

The bond, permit fees and annual reports are all current. Equipment at the site includes a bobcat, water truck, trailer, and sluice. There is no sign of recent activity. The site is stable.

The site is on SITLA ground but is accessed from BLM ground. In the past the BLM has expressed concerns about the access route and if a special use permit is needed. The Division will coordinate with the BLM as needed.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Directions to Site:

Coming from the east the access road is just past the Dugway Pass. From the west the access road is the last road going north before the pass.

Inspector's Signature


WHW:

cc: (OPERATOR)


Will Stokes - SITLA

O:\M023-Juab\S0230091-Dugwaypass\inspections\Insp-08232012.doc





Equipment included sluice and trailers



Bobcat



Power Auger



Sluice